POWERPOD STATUS LIGHT

PP connected to USB charger

Flashing red	PP charging
No light	PP fully charged
Flashing red/green	Isaac erasing PP ride memory

PP not connected to USB charger

Button is clicked, and the light shows:

Solid red	PP in new, "factory" condition
Solid yellow	PP ready for calibration ride
Solid green	PP is paired, calibrated, and ready to ride
No light after pressing button	PP battery is dead
Light goes out after solid green	PP has found sensors and is operating normally
Flashing green	PP has not found speed sensor
Flashing red	PP battery is low and needs recharging

Light goes out after solid green, cyclist starts riding, and light shows:

Flashing red without button push	PP battery is low and needs recharging

Light goes out after solid yellow, cyclist starts riding, and light shows:

Flashing yellow without button push	5-minute calibration is in progress
Flashing red/green (after solid yellow)	PP is ready for O&B calibration
Flashing yellow *after* button push	"Out" portion of O&B in progress
Solid red at the 50W mark of O&B ride	Stop, turn around, ride back
Flashing yellow *after* the 50W mark of O&B	"back" portion of O&B ride
Light goes out at end of cal ride	Calibration successfully completed
Light flashes yellow at the end of cal ride	Calibration failed; correct PP mounting angle & repeat

Light goes out after solid red, cyclist starts riding, and light shows:

No light	PP operating normally
Solid red after button push	PP not paired to speed sensor

Button is press-held for 4 seconds, and the light shows:

Flashing green	PP is performing sensor pairing process
3 flashes of red light during pairing	PP has "found" and ANT+ cadence sensor
3 flashes of yellow light during pairing	PP has "found" DFPM
Solid green, then goes out	PP has "found" speed sensor and pairing is complete

Button is press-held for 10 seconds, and the light:

Goes out, then starts flashing	PP has completed "hard-reset"

During a bike ride

No light	everything is normal
Flashing red	battery is low

Button is clicked 5 times in succession

Solid Green, then Yellow, then Red	PP goes to sleep; ride file is reset