



## PACKAGE CONTENTS




PowerPod Lite sensor




PowerPod mount and mounting hardware


## 1. Charge PowerPod




### 1A




## 2. Attach mount to bike




## 3. Attach PowerPod to mount




## 4. Pair PowerPod to ANT+ bike speed sensor



Spin front wheel  
to awaken speed sensor

**4A**


Press-hold button 4 sec. to pair

**4B**


Release button  
when **FLASHING GREEN**


**4C**


AFTER successful  
pairing light is  
**SOLID YELLOW**

**4D**



**RED:** Pairing unsuccessful

## 5. Pair PowerPod to your ANT+ bike computer



Refer to your ANT+ bike computer manual  
for pairing instructions

## 6. Calibrate




**SOLID YELLOW** light - ready to calibrate


**6A**

Flashing  
**red/green:**  
click to  
start  
O&B cal  
ride

Refer to O&B cal ride instructions sheet



**6B**

During out, watts go  
from 1 to 50;  
STOP, ride back  
to 100




After O&B complete, actual  
power shown


## 7. After Calibration



Light **FLASHES GREEN**

**7A**


Spin wheel, light changes to  
**SOLID GREEN**

**7B**


**GREEN MEANS GO!**