



PowerPod Instructions




PACKAGE CONTENTS




1. Charge PowerPod




1A Flashes **RED** during charge




1B Light off fully charged




2. Attach mount to bike



3. Attach PowerPod to mount




4. Pair PowerPod to ANT+ bike speed sensor




Spin sensor wheel to awaken speed sensor

4A




Press-hold button 4 sec. to pair

4B




Release button when **FLASHING GREEN**

4c




AFTER successful pairing light is **SOLID YELLOW**

4D




RED: pairing unsuccessful

5. Pair PowerPod to your ANT+ bike computer



Refer to your ANT+ bike computer manual for pairing instructions


6. Calibrate



SOLID YELLOW - ready to calibrate

6A


Click to start calibration ride when flashing **RED/GREEN**



Refer to *O&B cal ride instructions sheet*


6B

Ride out: watts go from 1 to 50; STOP, and ride back to 100




After calibration, actual power shown

7. Starting New Ride




Light **FLASHES GREEN**

7A



Spin wheel, light changes to **SOLID GREEN**

7B



GREEN MEANS GO!